

REF: 25X1A2g 7276 DTD 7 APR 67, PAR 68.

1. THE MAJOR LIMITING FACTORS EFFECTING A SECOND DEPLOYMENT FALLS IN THE AREA OF MATERIAL. MORE SPECIFICALLY, THE LACK OF CERTAIN ITEMS OF EQUIPMENT. THESE ARE:

A. SPARES:

SYSTEM 128-1, AMPLIFIER, 1 REQUIRED

REGA JANE, COMPLETE, DEPENDS ON MSN, NONE ON HAND

B. EQUIPMENT REQUIRED FOR 2ND GO:

FXR TEST OSCILLATOR 2650-5300 MC, 1 REQUIRED WAVEMETER DICO CAVITY SA-NL 6659, 1 REQUIRED SWITCH, SOLID STATE SADS528, 1 REQUIRED SWR METER H.P. 415D, 1 REQUIRED CARRIAGE, SLOTTED LINE HP809B, 1 REQUIRED COAXIAL SLOTTED SECTION HP806B, 1 REQUIRED UNTUNED PROBE HP444A, 2 REQUIRED SIGNAL GENERATOR HP614, 1 REQUIRED SIGNAL GENERATOR HP618B, 1 REQUIRED SIGNAL GENERATOR HP618B, 1 REQUIRED COUNTER ELECTRONIC HP5245L, 1 REQUIRED CONVERTER, PLUG-IN HP5253B, 1 REQUIRED REFLECTOMETER, TIME DOMAIN HP1415A, 1 REQUIRED

Approved For Release 1999/09/07 : CIA-RDP/11B00263R000200150091-2

Approved For Release 1999/09/07 : CIA-RDP71B0 63R000200150091-2 25X1A2g

IN 70957

0427

<del>0 5 0 5 5 5</del>

PAGE 2

OSCILLOSCOPE HP140A, 1 REQUIRED
CAMERA, SCOPE HP197A, 1 REQUIRED
METER, POWER HP431C, 1 REQUIRED
MOUNT, THERMISTOR HP478A, 1 REQUIRED
ATTENUATOR, VARIABLE HP382A, 1 REQUIRED
ATTENUATOR, VOLTAGE, VARIABLE CASCADE, RESEARCH
GYXOLINE MOD. R920, 1 REQUIRED
OSCILLOSCOPE, TEXTRONIC MOD RM561A, 1 REQUIRED
TIME BASE, PLUG-IN, TEXTRONIC MOD. 2B67, 1 REQUIRED
AMPLIFIER, PLUG-IN DUAL TRACE TEXTRONIC MOD. 3A1, 1 REQUIRED
METER, VOM TRIPLETT MOD. 310, 3 REQUIRED
TRACKER VIEWING STATION, 1 REQUIRED

- 2. TO A LESSER DEGRÉE, WE WOULD EXPERIENCE PROBLEMS IN LACK
  OF CERTAIN PERSONNEL AND IN OTHER AREAS INSUFFICIENT SUPERVISORY
  PERSONNEL TO PROPERLY OPERATE THE ARTICLES IN CONDUCTING ANY
  TESTS, TRAINING OR PROFICIENCY FLYING AT WITH MOST OF THE 25X1A2g
  PEOPLE ON DEPLOYMENT. THESE AREAS ARE:
- A. WE ONLY POSSESS ONE DOCTOR AND ONE WX OFFICER, THEY ARE NOW ON DEPLOYMENT.
- B. A SECOND DEPLOYMENT WOULD REQUIRE ONE OPS OFFICER. THIS

  WOULD LEAVE ONE OPS TYPE TO DIRECT OPERATIONS AT

  IF 25X1A29

  FLYING ACTIVITY IS LIMITED THIS POSES NO PROBLEM. OF TWO USAF

  FLIGHT PLANNERS AVAILABLE, ONE DEPARTS PCS IN JUNE. HE DESIRES

  LEAVE PRIOR TO DEPARTURE. HIS REPLACEMENT IS DUE TO ARRIVE IN JUNE

  BUT WILL REQUIRE SUPERVISION BEFORE BCOMING EFFECTIVE. WE HAVE

25X1A9aHEARD THAT MAY DEPART FOR PCS TO DURING JULY, 25X1A2g

AUGUST, SEPTEMBER PERIOD. THIS PRECLUDES SENDING QUALIFIED REPLACE-

- PLANNER IS ALSO SCHEDULED TO DEPART SHORTLY. THESE DEPARTURES WILL SERIOUSLY DEGRADE OUR FLIGHT PLANNING CAPABILITY UNTIL THIS FALL.
  - C. LIFE SUPPORT: MEDICAL AND PERSONAL EQUIPMENT PERSONNEL TECHNICIANS ARE AVAILABLE FOR A SECOND DEPLOYMENT. HOWEVER THERE

Approved For Release 1999/09/07: CIA-RDP/1B00263R000200150091-2

Approved For Release 1999/09/07 : CIA-RDP71B69263R000200150091-2 25X1A2q

WOULD BE MINIMUM LAUNCH SUPPORT CAPABILITY REMAINING AT

THE REMAINING PE TECH IS RECOVERING FROM A SERIOUS ILLINESS AND

IS NOT PHYSICALLY FIT FOR CONTINUOUS DUTY. A TDY PE TECH IS

ASSIGNED BUT HE IS NOT FULLY CHECKED OUT ON OUR EQUIPMENT.

ESTIMATE ANOTHER WEEK WILL BE REQUIRED TO FULLY CHECK OUT THIS

PE TECH. HOWEVER, ON 1 JUNE HE PLANS TO BE AWAY FROM

25X1A2g

FOR APPROX A TWO WEEK PERIOD TO BRING HIS FAMILY TO

25X1A6a

- D. AT THE MOMENT WE ONLY HAVE ONE STAFF AND THREE CONTRACT

  EMPLOYEES IN OUR SECURITY STAFF. THIS ONE STAFF EMPLOYEE IS

  PRESENTLY TDY WITH THE WE WOULD NEED HELP HERE. ASSUME 25X1A2g

  HQTRS COULD PROVIDE ASSISTANCE FROM OR OTHER. 25X1A2g
- 3. IN SUMMARY, BARRING THE EQUIPMENT LIMITATIONS NOTED
  ABOVE, AND THE LACK OF SOME PEOPLE (WHO, IN EVENT OF ANOTHER
  EPLOYMENT, WE ASSUME HQTRS COULD PROVIDE FROM OTHER SOURCES),
  WE ARE FULLY CAPABLE OF A SECOND DEPLOYMENT, HOWEVER, HOME PLATE
  ACTIVITIES WOULD BE AT A STANDSTILL FOR ALL PRACTICAL PURPOSES.
- 4. SORRY ABOUT BEING TARDY IN DEVELOPING THIS INFO FOR YOU.

  SECTION 052143Z MAY 67

DE ONE I